#### Shanghai Bomei Industrial Corporation Ltd.

No.181, 398 Lane, Changxi Road, Songjiang District, Shanghai 201612 China www.bomeiflor.com

# **Product Warranty**

Shanghai Bomei Industrial Corporation Ltd warrants that the **SOLID 1.0T** supplied against wear out is **5 years** under correct and proper transport, store, install and maintain method

#### **Conditions:**

- **1.** It must be specified according to Globalflor recommendations.
- **2.** Warranty is for products treated with polyurethane reinforcement.
- **3.** The original flooring material must be installed and maintained according to Globalflor flooring installation and maintenance instructions.
- **4.** A Globalflor flooring representative must be given the opportunity to inspect or arrange inspection of the installation prior to any action being taken.
- **5.** Warranty is valid for the original owner of the building and is non-transferable

### Globalflor flooring products are warranted against manufacturing defects subject to the following conditions:

- 1. Product that has obvious manufacturing defects should not be installed and a Globalflor flooring representative should be notified immediately if any obvious manufacturing defect is found.
- **2.** A Globalflor flooring representative must be given the opportunity to inspect the installation prior to any action being taken.
- **3.** Globalflor flooring warranty covers the cost of material only and does not cover costs associated with poor installation or inadequate maintenance.
- **4.** Globalflor flooring will supply replacement material for the affected area color matched from the current range as close as possible to the original design.

## The warranty is invalidated if the following occur:

- **1.** Damage caused by excessive surface moisture, flooding or hydrostatic pressure and other moisture related problems that may be present in the substrate.
- **2.** Scratching, cuts, gouges, staining, scuffs, burns, indentations, gloss reduction, reduction of the emboss and abuse of the flooring. Lack of appropriate protectors on furniture bases, table and chair legs or other items of furniture.
- **3.** Loss of adhesive bond due to high alkalinity in the sub-floor or contamination of the substrate as detailed in Globalflor flooring installation instructions.